

TRANS TECH CONSULTANTS

Environmental Compliance Services Engineers • Geologists • Planners License # 697833 (A-Haz)

September 1, 2005 Job No. 3057.01

Mr. Phillip Ostler 55 North Venice Blvd., Suite 503 Venice, California

Subject:

Well Abandonment Report

Former Fern Café - 606 Main Street, Ferndale, Califoria

LOP No. 12378; NCRWQCB Case No. 1THU378

Dear Mr. Ostler:

This letter presents the results of the monitoring well abandonment procedures performed at the subject site. The subject site is approximately located as shown on the Site Location Map, Plate 1. The work performed was in accordance with recommendations made in our May 24, 2005 Results of Investigation Report and concurred upon in a July 5, 2005 letter from Ms. Kasey Ashley of the North Coast Regional Water Quality Control Board (NCRWQCB).

On August 8 and 9, 2005, Trans Tech Consultants and Clear Heart Drilling, of Santa Rosa, California performed monitoring well abandonment procedures at the subject site. A total of six, 2-inch monitoring wells (MW-1 through MW-6) were abandoned under permit from the Humboldt County Department of Environmental Health. The locations of the former monitoring wells are shown on the Site Plan, Plate 2. Clear Heart Drilling is a C-57 licensed contractor, and the monitoring wells were abandoned in accordance with state and local guidelines. The wells seal and sand pack were over drilled using hollow stem auger equipment. The PVC well casings were then removed from the hole and the holes were then backfilled with a portland cement grout. The surface was restored with asphalt or concrete as appropriate. The metal well boxes, the concrete seals and the PVC casings were separated from the drill cuttings and disposed of in onsite garbage bins. The remainder of the drill cuttings were stored in three 55-gallon drums and stored onsite, pending disposal. In addition, two 55-gallon drums of rinsate water were generated as a result of the well abandonment procedures. The five drums will be combined with the existing onsite drums of soil and water generated from previous investigations and disposed of under manifest at an approved facility as soon as possible. The disposal documentation for the soil and water will be provided as soon as disposal is performed.

We trust that this provides the information you require at this time and we appreciate the opportunity to be of service to you. If you have any questions or require any additional information, please feel free to contact us at (707) 575-8622 or www.transtechconsultants.com.

No. 7573 Exp. 05/31/07

Sincerely,

TRANS TECH CONSULTANTS

Lee S. Hurvitz, PG 7573


Professional Geologist

Attachments: Plate 1,

Site Location Map

Plate 2, Site Plan

Distribution List




930 SHILOH RD., BLDG 44, SUITE J WINDSOR, CA 95492 PHONE: 707-575-8622 FAX: 707-837-7334

FERNDALE, CALIFORNIA

DRAWN BY: DWG NAME: APPR. BY: 3057.01.03 SLM **PSC** LSH

JOB NUMBER: 3057.01.03 W.O. NUMBER: REVISIONS: A-212

DATE: 8/25/03



DISTRIBUTION LIST Monitoring Well Abandonment Report Former Fern Café 606 Main Street Ferndale, California September 1, 2005 Job No. 3057.01

Mr. Mark Verhey Humboldt County Department of Public Health Division of Environmental Health 100 H Street, Suite 100 Eureka, California 95501

Ms. Kasey Ashley North Coast Regional Water Quality Control Board 5550 Skylane Boulevard, Suite A Santa Rosa, California 95403